

Priority Facility Needs

Critical	Important	Enhancements
<p>3-story elevator, large enough for set pieces, orchestra stands and chairs, etc.</p> <p>Serve cast, crew & audience needs</p>	<p>Mid-size performing space (200-500 seats)</p>	<p>Rehearsal space</p>
<p>Renovation of the basement</p> <ul style="list-style-type: none"> • Replace staircase • Renovate/replace dressing rooms & bathrooms • Improve storage accessibility • Evaluate shop space, ceiling height is inadequate • Improve lighting 	<p>Lighting board and positions</p>	<p>Kitchen for the reception space and concessions</p>
<p>Audience restrooms are totally inadequate in number and in appearance.</p>	<p>Additional, larger reception space</p>	<p>A smaller meeting space</p>
<p>Rigging: possible safety issues</p>	<p>New pit cover that can be used as performance space</p>	
<p>Lobby is too small for large houses</p>	<p>Public access to the gallery</p>	

Priority Facility Needs

Critical	Important	Enhancements
<p>Sound system, groups currently supply their own</p> <p>Include recording capability as part of the system</p> <p>Re-evaluate the existing shell, it does not meet all the orchestra needs and is difficult to install & store</p>	<p>Improved and enhanced signage</p>	
<p>Because the building was renovated 17 years ago, there is a lot of maintenance that is needed to really restore it.</p>	<p>Secure, humidity & temperature controlled storage for instruments</p>	
<p>Handicapped seating that doesn't block the seats behind them</p>	<p>Improved signage, the marquee is small, alternative needs to be developed</p>	
<p>HVAC needs a total overhaul</p>	<p>Computer networking for the groups in the offices and ECRAC</p>	
<p>All stairs have turns, need to be re-oriented</p>	<p>Improve lighting outside the building by entrances</p>	

Priority Facility Needs

Critical	Important	Enhancements
Load-in door is inadequate, no loading dock	Office space needs to be expanded	
	Improve box office for night of shows and for advance pick-up	
2nd Floor needs		
Elevator for students and improved stairs Find a way to provide better access for students when the building is locked	Improve general maintenance	
Sound proofing	Would be used 6-12 times per year	
Heat goes off at 5:00 but classes continue through 10:00 p.m . Make it clearer that the classrooms and offices are there.	Mid-size performing space (200-500 seats) for recitals	
Improved lighting in halls, storage areas and offices		
Make it clearer that the classrooms and offices are there.		
Find a way to provide better access for students when the building is locked		

Priority Facility Needs

Critical	Important	Enhancements
	A ticket pick-up process that is better than having people climb the stairs ..	
	Improve lighting outside the building by entrances	
	Improved signage and directions to the classrooms	
	Gift Shop for theatre and the gallery	
	Hi-speed computer network	
	Parking is a problem when there are shows on the stage	
	If a smaller performing space is provided, these groups would echo the concerns about the basement level restrooms, dressing rooms, etc	